

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 02/14/2012  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155608</b>		(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01 , 02</b> B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>02/09/2012</b>	
NAME OF PROVIDER OR SUPPLIER  <b>WITTENBERG LUTHERAN VILLAGE</b>				STREET ADDRESS, CITY, STATE, ZIP CODE <b>1200 E LUTHER DR</b> <b>CROWN POINT, IN 46307</b>			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
{K 000}	<p>INITIAL COMMENTS</p> <p>A Post Survey Revisit (PSR) to the Comparative Federal Monitoring Survey conducted on 11/28/11 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 02/09/11</p> <p>Facility Number: 000525 Provider Number: 155468 AIM Number: 100267010</p> <p>Surveyor: Bridget Brown, Life Safety Code Specialist</p> <p>At this PSR survey, Wittenberg Lutheran Village was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies.</p> <p>The original one story building with a partial basement identified as building 102 was determined to be to be of Type II (000) construction and was partially sprinklered. The unsprinklered Chapel/Fellowship Hall identified as building 202 was determined to be Type V (000) construction and occupies a 1990 wing addition to the facility. The facility is surveyed as two buildings due to different construction types.</p> <p>The facility has a fire alarm system with smoke detection in the corridors and spaces open to the corridors with battery powered smoke detectors in resident rooms. The facility has the capacity for 155 and had a census of 146 at the time of this</p>			{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 02/14/2012  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155608</b>		(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01 , 02</b> B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>02/09/2012</b>	
NAME OF PROVIDER OR SUPPLIER  <b>WITTENBERG LUTHERAN VILLAGE</b>				STREET ADDRESS, CITY, STATE, ZIP CODE <b>1200 E LUTHER DR</b> <b>CROWN POINT, IN 46307</b>			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
{K 000}	<p>Continued From page 1 survey.</p> <p>Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 02/13/12. A Post Survey Revisit (PSR) to the Comparative Federal Monitoring Survey conducted on 11/28/11 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 02/09/11</p> <p>Facility Number: 000525 Provider Number: 155468 AIM Number: 100267010</p> <p>Surveyor: Bridget Brown, Life Safety Code Specialist</p> <p>At this PSR survey, Wittenberg Lutheran Village was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies.</p> <p>The original one story building with a partial basement identified as building 102 was determined to be to be of Type II (000) construction and was partially sprinklered. The unsprinklered Chapel/Fellowship Hall identified as building 202 was determined to be Type V (000) construction and occupies a 1990 wing addition to the facility. The facility is surveyed as two buildings due to different construction types.</p> <p>The facility has a fire alarm system with smoke detection in the corridors and spaces open to the</p>			{K 000}			

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 02/14/2012  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155608</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01 , 02</b> B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>02/09/2012</b>
NAME OF PROVIDER OR SUPPLIER  <b>WITTENBERG LUTHERAN VILLAGE</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>1200 E LUTHER DR</b> <b>CROWN POINT, IN 46307</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	Continued From page 2 corridors with battery powered smoke detectors in resident rooms. The facility has the capacity for 155 and had a census of 146 at the time of this survey.	{K 000}			